








2025-12-15



SANTIAGO corner




a. x 4 MME00202	b. x 2 MOI00101	c. x 6 MME00197	d. x 6 MME00197	e. x 1 "4" MIW00062
f. x 10 Ø50x50 MON01103	g. x 6 Ø45x15 MON0341	h. x 14 M6x25 MME00206	i. x 24 M6x20 MME00189	j. x 10 4,5x40 MME00076
k. x 6 5x60 MME00287	l. x 4 Ø35x7 MOI00095			





L 1-5



R 6-10



I			
g. x 6	Ø45x15		
f. x 2	Ø50x50		
j. x 6	4,5x40		
k. x 2	5x60		




2025-12-15

SANTIAGO corner

II

L



h. x 6








M6x25

e. x 1




"4"



2025-12-15

SANTIAGO corner

III



c. x 2

d. x 2





f. x 2 Ø50x50

i. x 8 M6x20


k. x 2 5x60

e. x 1 "4"

L



IV






a. x 2

b. x 2

h. x 4 M6x25

e. x 1 "4"


L




2025-12-15

SANTIAGO corner

V



c. x 4



f. x 4



Ø50x50

i. x 8



M6x20

j. x 4



4,5x40


e. x 1




"4"




L



VI



a. x 2



h. x 4



M6x25

l. x 4




Ø35x7

e. x 1



"4"


L




2025-12-15

SANTIAGO corner

VII



d. x 4



f. x 2



Ø50x50

k. x 2




5x60

i. x 8



M6x20





e. x 1




"4"






L




VIII




L



L




OK



2025-12-15

SANTIAGO corner

I





R

g. x 6  Ø45x15

f. x 2  Ø50x50

j. x 6  4,5x40

k. x 2  5x60




2025-12-15

SANTIAGO corner

II

R



h. x 6








M6x25

e. x 1




"4"





2025-12-15

SANTIAGO corner

III




c. x 2 

d. x 2 


f. x 2  Ø50x50

i. x 8  M6x20


k. x 2  5x60

e. x 1  "4"

R



IV





a. x 2 

b. x 2 

h. x 4  M6x25

e. x 1  "4"


R




2025-12-15

SANTIAGO corner

V



c. x 4



f. x 4



Ø50x50

i. x 8



M6x20

j. x 4



4,5x40



e. x 1




"4"



R



VI



a. x 2



h. x 4



M6x25

l. x 4





Ø35x7

e. x 1



"4"


R




2025-12-15

SANTIAGO corner

VII



d. x 4



f. x 2



Ø50x50

k. x 2



5x60

i. x 8




M6x20




e. x 1




"4"






R




VIII



R



R



OK

